
REPLACEMENT SHEET METHOD FOR REMOVING OXIDE FROM CRACKS IN TURBINE COMPONENTS LAWRENCE BERNARD KOOL, ET AL. SERIAL NO. 10/749,486 ATTORNEY DOCKET NO. 136983-1


Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002

1/3



ATTORNEY DOCKET NO. 136983-1 Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002

2/3



3/3




FIG. 6